



---

**Northern Airborne Technology Ltd.**

1925 Kirschner Road, Kelowna, BC Canada V1Y 4N7  
Tel: 250.763.2232 • Toll Free: 888.763.2232 • Fax: 250.762.3374  
[www.northernairborne.com](http://www.northernairborne.com)

**Beacon Product Repair Service Discontinuation Notice**

Effective July 1, 2008, Northern Airborne Technology Ltd. is no longer supporting repair service of the following Emergency Position Indicating Radio Beacon (EPIRB), Global Position Indicating Radio Beacon (GPIRB) and Personal Locator Beacon (PLB) products:

EPIRB's: S1000, S1005, S1010, S1015, S1020, S1025  
GPIRB's: S1500, S1505, S1510, S1515  
PLB's: L2000, L2001, L2100, L2101

Further information; battery replacement service for the EPIRB and GPIRB models listed above and; RSA-001, RSA-001A, RSA-002 and RSA-002A release mechanisms are available from:

CMC Electronics, Esterline  
40 Thornhill Drive, #6  
Dartmouth, NS  
Canada  
B3B 1S1  
Attn: Deborah MacAulay – Parts and Service Representative

Phone: (902) 468-8480, ext. 30  
Toll Free: 1-800-565-2099  
Fax: (902) 468-8484

We at NAT would like to thank you for your business and apologize for any inconvenience this may cause. We are confident CMC Electronics will continue to provide excellent customer service for the EPIRB and GPIRB products above.

Yours very truly,

Daryl Shauer,  
VP QA and Operations